



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining


MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

June 5, 2008

Supervisor 

<b>Mine Name:</b> C and R Mill	<b>Permit Number:</b> S0190024
<b>Operator Name:</b> Cand R minerals	<b>Inspection Date:</b> 05/08/2008
<b>Inspector(s):</b> Tom Munson	<b>Time:</b> 10AM-11AM
<b>Other Participants:</b> none	<b>Mine Status:</b> abandoned

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

The purpose of this inspection is to determine the extent of the potential hazards related to this property. The site has been abandoned for a number of years having been originally permitted in 1990 by Ken Cooper of Cand R Minerals.


#### Inspection Summary:

The site is gated so one cannot drive to the site but can access it by a short walk. It is visible from the highway. The site has much mining related impact and remains a mess from past disturbance. The site has an abandoned building, an open well, abandoned mining equipment, trash and excavations. This site was permitted in 1990. There appears to be some confusion in the database about this site and the delinquent permit fees were sent to collections in 2001. There has been no resolution of the matter since this action. The site remains a total mess and should be cleaned up. It will take some research to determine the responsible party.

Photos were taken to document site conditions.

#### Conclusions and Recommendations:

The Division is requesting that the operator pay past due permit fees or perform reclamation within 60 days.

Inspector's Signature 

TM:pb

cc: (OPERATOR)

O:\M019-Grand\S0190024-CandRMinerals\inspections\insp-S190024-05092008.doc